



Intel® Desktop Board D815EFV/D815EPFV Specification Update

Release Date: October 2002

Order Number: A56560-012

The desktop board D815EFV/D815EPFV may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are documented in this Specification Update.

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL® PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER, AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT. Intel products are not intended for use in medical, life saving, life sustaining applications.

Intel may make changes to specifications and product descriptions at any time, without notice.

Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them.

The Intel® desktop board D815EFV/D815EPFV may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications before placing your product order.

Copies of documents which have an ordering number and are referenced in this document, or other Intel literature, may be obtained from:

Intel Corporation
P.O. Box 5937
Denver, CO 80217-9808

or call in North America 1-800-548-4725, Europe 44-0-1793-431-155, France 44-0-1793-421-777,
Germany 44-0-1793-421-333, other Countries 708-296-9333

Intel, Pentium, Celeron, LANDesk and the Intel logo are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

* Other names and brands may be claimed as the property of others.

Copyright © 2001, 2002 Intel Corporation.

CONTENTS

REVISION HISTORY	v
PREFACE	vi
Specification Update for Desktop Board D815EFV/D815EPFV	
GENERAL INFORMATION	3
SPECIFICATION CHANGES	6
ERRATA.....	8
SPECIFICATION CLARIFICATIONS.....	11



REVISION HISTORY

Date of Revision	Version	Description
April 2001	-001	This document is the first Specification Update for the Intel® Desktop Board D815EFV/D815EPFV. Added Documentation Changes 1-7.
May 2001	-002	Added Erratum 1.
June 2001	-003	Removed Document Changes 1-7, which were published in revision -002 of the Technical Product Specification. Added Erratum 2.
August 2001	-004	Updated General Information Section.
September 2001	-005	Added Erratum 3.
October 2001	-006	Added Erratum 4.
November 2001	-007	Added Specification Change 1. Updated Erratum 3.
January 2002	-008	Added Specification Clarifications 1, 2.
February 2002	-009	Added Erratum 5.
April 2002	-010	Added Erratum 6.
September 2002	-011	Removed Printed Board Assembly (PBA) information from the document, as this reference is no longer valid. Updated Legal Disclaimer Section.
October 2002	-012	Added Erratum 7.



PREFACE

This document is an update to the specifications contained in the *Desktop Board D815EFV/D815EPFV Technical Product Specification* (Order number A49745). It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools. It will contain Specification Changes, Errata, Specification Clarifications, and Documentation Changes.

Refer to the *Intel® Pentium® III Processor Specification Update* (Order number 244453) for specification updates concerning the Intel Pentium 4 processor and that may apply to the desktop board D815EFV/D815EPFV. Unless otherwise noted in this document, it should be assumed that any processor errata for a given stepping are applicable to the Altered Assembly (AA) revision(s) associated with that stepping.

Refer to the *Intel® Celeron® Processor Specification Update* (Order number 243748) for specification updates concerning the Intel Pentium 4 processor and that may apply to the desktop board D815EFV/D815EPFV. Unless otherwise noted in this document, it should be assumed that any processor errata for a given stepping are applicable to the Altered Assembly (AA) revision(s) associated with that stepping.

Refer to the *Intel® 815 Chipset Family: 82815 GMCH Specification Update for Use with the Universal Socket 370* (Order Number 298307) for specification updates concerning the 82815E GMCH Controller and that may apply to the desktop board D815EFV/D815EPFV. Unless otherwise noted in this document, it should be assumed that any GMCH errata for a given stepping are applicable to the Altered Assembly (AA) revision(s) associated with that stepping.

Refer to the *Intel® 82801BA I/O Controller Hub 2 (ICH2) and Intel® 82801BAM I/O Controller Hub 2 Mobile (ICH2-M) Specification Update* (Order Number 298242) for specification updates concerning the 82801BA I/O Controller Hub and that may apply to the desktop board D815EFV/D815EPFV. Unless otherwise noted in this document, it should be assumed that any ICH 2 errata for a given stepping are applicable to the Altered Assembly (AA) revision(s) associated with that stepping.

Nomenclature

Specification Changes are modifications to the current published specifications. These changes will be incorporated in the next release of the specifications.

Errata are design defects or errors. Characterized errata may cause the desktop board D815EFV/D815EPFV behavior to deviate from published specifications. Hardware and software designed to be used with any given Altered Assembly (AA) and BIOS revision level must assume that all errata documented for that AA and BIOS revision level are present on all desktop boards.

Specification Clarifications describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in the next release of the specifications.

Documentation Changes include typos, errors, or omissions from the current published specifications. These changes will be incorporated in the next release of the specifications.

**Specification Update for
Desktop Board D815EFV/D815EPFV**

GENERAL INFORMATION

Basic Desktop Board D815EFV/D815EPFV Identification Information

AA Revision	BIOS Revision	Notes
A45150-204	EA81520A.86A.0006.P03	1-6
A45150-205	EA81520A.86A.0007.P04	1-6
A45150-206	EA81520A.86A.0007.P04	1-6
A45150-207	EA81520A.86A.0015.P10	1-6
A45150-208	EA81520A.86A.0021.P13	1-6
A45152-204	EA81520A.86A.0006.P03	1-6
A45152-205	EA81520A.86A.0006.P03	1-6
A45152-206	EA81520A.86A.0015.P10	1-6
A45152-207	EA81520A.86A.0021.P13	1-6
A46427-204	EA81520A.86A.0006.P03	1-6
A46427-205	EA81520A.86A.0006.P03	1-6
A46427-206	EA81520A.86A.0015.P10	1-6
A46427-207	EA81520A.86A.0021.P13	1-6
A54455-204	EA81520A.86A.0006.P03	1-6
A54455-205	EA81520A.86A.0015.P10	1-6
A54455-206	EA81520A.86A.0021.P13	1-6
A51500-802	EA81520A.86A.0019.P12	1-6
A51500-803	EA81520A.86A.0028.P15	1-6
A51497-802	EA81520A.86A.0019.P12	1-6
A51493-802	EA81520A.86A.0019.P12	1-6

NOTES:

1. The AA number is found on a small label on the component side of the board.
2. The 82815 Chipset kit used on this AA revision consists of three components as follows:



Device	Stepping	S-Spec Numbers
82815 GMCH or	A2 B0 A2T	SL4DF SL5NQ SL5YN
82815EP MCH	A2 B0	SL552 SL5NR
82801BA ICH	B1 B0	SL4HM SL5FC
82802AB FWH or STM M50FW040 FWH	A0 NA	SB48 NA

3. Refer to the *Intel® Pentium® III Processor Specification Update* (Order number 244453) for errata related to the Pentium 4 processor and that may apply to the desktop board D815EFV/D815EPFV.
4. Refer to the *Intel® Celeron® Processor Specification Update* (Order number 243748) for errata related to the Pentium 4 processor and that may apply to the desktop board D815EFV/D815EPFV.
5. Refer to the *Intel® 815 Chipset Family: 82815 GMCH Specification Update for Use with the Universal Socket 370* (Order Number 298307) for errata related to the 82815E MCH that may apply to the desktop board D815EFV/D815EPFV.
6. Refer to the *Intel® 82801BA I/O Controller Hub 2 (ICH2) and Intel® 82801BAM I/O Controller Hub 2 Mobile (ICH2-M) Specification Update* (Order Number 298242) for errata related to the 82801BA I/O Controller Hub that may apply to the desktop board D815EFV/D815EPFV.

Summary Table of Changes

The following table indicates the Specification Changes, Errata, Specification Clarifications, or Documentation Changes which apply to the desktop board D815EFV/D815EPFV. Intel intends to fix some of the errata in a future revision of the desktop board, and to account for the other outstanding issues through documentation or specification changes as noted. This table uses the following notations:

CODES USED IN SUMMARY TABLE

- Doc: Document change or update that will be implemented.
- Fix: This erratum is intended to be fixed in a future revision of the desktop board or BIOS.
- Fixed: This erratum has been previously fixed.
- NoFix: There are no plans to fix this erratum.
- Shaded: This erratum is either new or modified from the previous version of the document.

NO.	PLANS	SPECIFICATION CHANGES
1	Doc	Support for faster Intel® Pentium® III processors
NO.	PLANS	ERRATA
1	Fixed	Intel Pentium III processor Erratum E76
2	Fix	System BIOS will not properly configure multi-channel audio Communications Network Riser (CNR) cards
3	Fixed	Communication Network Riser (CNR) LAN devices may not respond upon returning from S4 or S5 ACPI sleep states
4	Fixed	Advanced Power Management (APM) Feature set to disabled in the BIOS Setup Menu will cause system reboot if the user attempts a system shutdown during POST
5	Fixed	System hang during POST may occur when using certain USB cameras
6	Fixed	System hangs or video corruption will occur resuming from ACPI S3 sleep state when using BIOS Revisions EA81520A.86A.0028.P15 or EA81520A.86A.0030.P16 and certain AGP video adapters
7	Fixed	Wake from an ACPI sleep state using wake methodologies may fail
NO.	PLANS	SPECIFICATION CLARIFICATIONS
1	Doc	Change to description of Section 2.6, Interrupts
2	Doc	Change to description of Section 2.7, PCI Interrupt Routing Map

SPECIFICATION CHANGES

The Specification Changes listed in this section apply to the *D815EFV/D815EPFV Desktop Board Technical Product Specification* (Order Number A49745). All Specification Changes will be incorporated into a future version of that specification.

1. Support For Faster Intel® Pentium® III Processors

Section 1.6, Processor, will change in its entirety as follows:

1.6 Processor



CAUTION

Use only the processors listed below. Use of unsupported processors can damage the board, the processor, and the power supply. See the Intel® Desktop D815EFV/D815EPFV Specification Update for the most up-to-date list of supported processors for the D815EFV and D815EPFV boards.

The D815EFV and D815EPFV boards both support a single Pentium® III or Celeron® processor. The system bus frequency is automatically selected. The D815EFV and D815EPFV boards support the processors listed in Table 1.

Table 1. Supported Processors

Type	Designation	System Bus Frequency	L2 Cache Size
Pentium® III processor in an FC-PGA package	533EB, 600EB, 667, 733, 800EB, 866, and 933 MHz	133 MHz	256 KB
	1.0, and 1.2 GHz		
	500E, 550E, 600E, 650, 700, 750, 800, and 850, MHz	100 MHz	256 KB
	1.1 GHz		
Celeron® processor in an FC-PGA package	800, 850, 900, and 950 MHz	100 MHz	128 KB
	1.1 GHz		
	533A, 566, 600, 633, 667, 700, 733, and 766 MHz	66 MHz	128 KB



NOTE

BIOS revision EA81520A.86A.0028.P12 or greater and board revisions A51500-700 or greater are required for the board to properly support 1.2 GHz Pentium® III or later processors.



NOTE

BIOS revision EA81520A.86A.0019.P12 or greater is required for the board to properly support 900 MHz Celeron® or later processors.

All supported onboard memory can be cached, up to the cachability limit of the processor. See the processor's data sheet for cachability limits.

For information about	Refer to
Product information on supported processors	Section 1.3, page 18
Processor data sheets	Section 1.3, page 18

ERRATA

1. **Intel® Pentium® III Processor Erratum E76**

PROBLEM: For a complete description of the Pentium® III processor erratum E76, see the Pentium III Specification Update, order number 244453 found at <http://developer.intel.com/design/PentiumIII/specupdt/>.

IMPLICATION: For a complete description of the Pentium III processor erratum E76, see the Pentium III Specification Update, order number 244453 found at <http://developer.intel.com/design/PentiumIII/specupdt/>.

WORKAROUND: Update the D815EFV/D815EPFV desktop board with BIOS revision EA81520A.86A.0014.P09.

STATUS: This erratum was addressed in BIOS revision EA81520A.86A.0014.P09.

2. **System BIOS Will Not Properly Configure Multi-Channel Audio Communications Network Riser (CNR) Cards**

PROBLEM: During the system boot process, the system BIOS compares the multi-channel signature stored in BIOS with the multi-channel signature stored in the audio CNR EEPROM. If the signatures match, the system BIOS then programs the device ID in the PCI configuration space with the multi-channel model ID from the CNR EEPROM. The system BIOS for this desktop board incorrectly programs the device ID in the PCI configuration space. When the audio driver that supports multi-channel functionality is installed, the driver may not install correctly or may not install at all.

IMPLICATION: Users who install a multi-channel audio CNR card may experience difficulty installing the manufacturers audio drivers.

WORKAROUND: None.

STATUS: This erratum is intended to be fixed in a future BIOS revision.

3. **Communication Network Riser (CNR) LAN Devices May Not Respond Upon Returning From S4 or S5 ACPI Sleep States**

PROBLEM: CNR LAN devices may not correctly resume from an S4 or S5 ACPI sleep state, even though the Microsoft Windows* operating system device manager indicates the device is working properly.

IMPLICATION: Users utilizing an add-in CNR LAN adapter with ACPI enabled may experience a loss of network connectivity after the system resumes from an ACPI S4 or S5 sleep state.

WORKAROUND: After resuming from the ACPI sleep state, the system will need to be restarted so that the CNR LAN device can be re-enumerated.

STATUS: This erratum was fixed in BIOS revision EA81520A.86A.0021.P13.

4. Advanced Power Management (APM) Feature Set to Disabled in The BIOS Setup Menu Will Cause System Reboot if The User Attempts a System Shutdown During POST

PROBLEM: If the APM function is set to disabled in the BIOS setup menu and the user attempts a system shutdown during POST, the system will reboot instead of shutting down.

IMPLICATION: Users who wish to perform a system shutdown during POST will experience a reboot and not a system shutdown as expected if the APM function is set to disabled in the BIOS setup menu.

WORKAROUND: None.

STATUS: This erratum was fixed in BIOS revision EA81520A.86A.0021.P13.

5. System Hang During POST May Occur When Using Certain USB Cameras

PROBLEM: During the system boot, certain USB cameras may cause a hang during POST if the camera is on during the boot process.

IMPLICATION: Some USB cameras may cause a system hang if the camera is on during system boot due to the BIOS incorrectly identifying the camera as a bootable device.

WORKAROUND: Ensure that the USB camera is off during the system boot process.

STATUS: This erratum was fixed in BIOS revision EA81520A.86A.0030.P16.

6. System Hangs or Video Corruption Will Occur Resuming From ACPI S3 Sleep State When Using BIOS Revisions EA81520A.86A.0028.P15 or EA81520A.86A.0030.P16 And Certain AGP Video Adapters

PROBLEM: With BIOS revisions EA81520A.86A.0028.P15 or EA81520A.86A.0030.P16, system hangs or video corruption will occur resuming from ACPI S3 sleep state while using certain graphics adapters.

IMPLICATION: Users that utilize the ACPI S3 sleep state in conjunction with Bios revisions EA81520A.86A.0028.P15 or EA81520A.86A.0030.P16 will experience system hangs or video corruption with certain AGP video adapters.

WORKAROUND: None.

STATUS: This erratum was fixed in BIOS revision EA81520A.86A.0031.P17.

7. Wake From an ACPI Sleep State Using Wake Methodologies May Fail

PROBLEM: The desktop board hardware leaves the Resume Well Power OK (RSM_PWROK) signal deasserted before and after the resume well power (VccSus3_3 and VccSus1_8) is valid, instead of asserting it for 10 ms after valid power, which is required by the Intel® 82801BA I/O Controller Hub 2 (ICH2) and Intel® 82801BAM I/O Controller Hub 2 Mobile (ICH2-M) Datasheet (order number 290687). The result is that LAN wake attempts may fail.



NOTE: Wake from LAN* using the MagicPacket* utility will not be affected by this errata.

IMPLICATION: Users that take advantage of LAN wake methods to wake systems from an ACPI sleep state may experience some wake failures.

WORKAROUND: None.

STATUS: This issue was fixed in BIOS revision EA81520A.86A.0037.P19.

SPECIFICATION CLARIFICATIONS

The Specification Changes listed in this section apply to the *D815EFV/D815EPFV Desktop Board Technical Product Specification* (Order Number A49745). All Specification Changes will be incorporated into a future version of that specification.

1. **Change to Description of Section 2.6, Interrupts**

Section 2.6, Interrupts, will change in its entirety as follows:

2.6 **Interrupts**

The Interrupts can go through either the Programmable Interrupt Controller (PIC) or the Advanced Programmable Interrupt Controller (APIC) portion of the Intel® ICH2 component. The PIC is supported in Windows* 98 SE and Windows ME and uses the first 16 interrupts. The APIC is supported in Windows 2000 and Windows XP and support a total of 24 interrupts.

Table 17. Interrupts

IRQ	System Resource
NMI	I/O channel check
0	Reserved, interval timer
1	Reserved, keyboard buffer full
2	Reserved, cascade interrupt from slave PIC
3	COM2 (Note 1)
4	COM1 (Note 1)
5	LPT2 (Plug and Play option) / User available
6	Diskette drive
7	LPT1 (Note 1)
8	Real-time clock
9	Reserved for Intel ICH2 system management bus
10	User available
11	User available
12	Onboard mouse port (if present, else user available)
13	Reserved, math coprocessor
14	Primary IDE (if present, else user available)
15	Secondary IDE (if present, else user available)

continued

Table 17. Interrupts (continued)

IRQ	System Resource
16	AGP video (through PIRQA) ^(Note 2)
17	AC' 97 Audio/User Available (through PIRQB) ^(Note 2)
18	User available (through PIRQC) ^(Note 2)
19	Intel® ICH2 USB Controller #1 (through PIRQD) ^(Note 2)
20	Intel ICH2 LAN (optional) (through PIRQE) ^(Note 2)
21	User available (through PIRQF) ^(Note 2)
22	User available (through PIRQG) ^(Note 2)
23	Intel ICH2 USB Controller #2/ User Available (through PIRQH) ^(Note 2)

Note 1: Default, but can be changed to another IRQ.

Note 2: Available in APIC mode only.

2. *Change to Description of Section 2.7, PCI Interrupt Routing Map*

Section 2.7, PCI Interrupt Routing Map, will change in its entirety as follows:

2.7 *PCI Interrupt Routing Map*

This section describes interrupt sharing and how the interrupt signals are connected between the PCI bus connectors and onboard PCI devices. The PCI specification specifies how interrupts can be shared between devices attached to the PCI bus. In most cases, the small amount of latency added by interrupt sharing does not affect the operation or throughput of the devices. In some special cases where maximum performance is needed from a device, a PCI device should not share an interrupt with other PCI devices. Use the following information to avoid sharing an interrupt with a PCI add-in card.

PCI devices are categorized as follows to specify their interrupt grouping:

- **INTA:** By default, all add-in cards that require only one interrupt are in this category. For almost all cards that require more than one interrupt, the first interrupt on the card is also classified as INTA.
- **INTB:** Generally, the second interrupt on add-in cards that require two or more interrupts is classified as INTB. (This is not an absolute requirement.)
- **INTC and INTD:** Generally, a third interrupt on add-in cards is classified as INTC and a fourth interrupt is classified as INTD.

The Intel® ICH2 has eight programmable interrupt request (PIRQ) input signals. All PCI interrupt sources either onboard or from a PCI add-in card connect to one of these PIRQ signals. Some PCI interrupt sources are electrically tied together on the D815EFV and D815EPFV boards and therefore share the same interrupt. Table 18 shows an example of how the PIRQ signals are routed on the D815EFV and D815EPFV boards.

For example, using Table 18 as a reference, assume that an add-in card using INTA is plugged into PCI bus connector 3. In PCI bus connector 3, INTA is connected to PIRQH, which is already connected to the Intel ICH2 USB controller #2. The add-in card in PCI bus connector 3 now shares interrupts with these onboard interrupt sources.

Table 28. PCI Interrupt Routing Map

PCI Interrupt Source	ICH PIRQ Signal Name				
	PIRQF	PIRQG	PIRQH	PIRQB	Other
GMCH/AGP				INTB	INTA to PIRQA
Intel ICH2 USB controller #1					INTD to PIRQD
SMBus controller				INTB	
Intel ICH2 USB controller #2			INTC		
Intel ICH2 audio/modem				INTB	
Intel ICH2 LAN					INTA to PIRQE
PCI bus connector 1 (J7B1)	INTA	INTB	INTC	INTD	
PCI bus connector 2 (J8B2)	INTD	INTA	INTB	INTC	
PCI bus connector 3 (J9B2)	INTC	INTD	INTA	INTB	

NOTE

In PIC mode, the Intel ICH2 can connect each PIRQ line internally to one of the IRQ signals (3, 4, 5, 6, 7, 9, 10, 11, 12,14, and 15). Typically, a device that does not share a PIRQ line will have a unique interrupt. However, in certain interrupt-constrained situations, it is possible for two or more of the PIRQ lines to be connected to the same IRQ signal. In APIC mode, the allocation of PIRQ lines to IRQ signals is as shown in Table 18.